
SLOAN REGAL

COMPETITIVE STYLE





1	#08083	R10	C.P. Cover
2	#08050	A71	Inside Cover
	#08004	A19AC	Closet R. Valve(White)
	#08005	A19AU	Urinal R. Valve(Black)
3	#08345	A19ALC CI	oset/Urinal R. Valve(Green)
4	#08003	A15A	Molded Disc
5	#08002	A156A	Diaphragm
ADJUSTABLE GUIDES			
	#08006	A163A	Standard Guide
_	#08252	A152A	For 3.5 GPF Closet
6	#08348	A151A	For 1.6 GPF Closet
	#08349	A155A	For 1.0 GPF Urinal
7	#08000	A38A	3.5 Closet Water Saver Kit
′	#08114	A41A 1	1.6 Closet Low Consumption
0	#08001	A37A	Urinal Retro Kit - 1.5 GPF
8	#08115	A42A	Urinal Retro Kit - 1.0 GPF
9	#08007	B50A	Handle Repair Kit (Plastic)
40	#08008	B32A	C.P. Handle Assy.
10	#08069	B73A	A.D.A. Handle Assy.
11	#08054	A6	C.P. Handle Nut
12	#08012	V551A	V/B Repair Kit
CHROME PLATED VACUUM BREAKERS			
	#08014	V500AA	1-1/2" x 9" Closet
13	#08015	V500AA	1-1/4" x 9" Urinal
	#08016	V500AA	3/4" x 9" Urinal
	#08020		1-1/2" Gasket Kit
14	#08021		1-1/4" Gasket Kit
	#08022		3/4" Gasket Kit
	#08142	F56A	1-1/2" Coupling Assy
15	#08143	F55A	1-1/4" Coupling Assy
	#08144	F54A	3/4" Coupling Assy
16	#08040	H550	Tailpiece Coupling Nut
17	#08039	H551A	Adj. Tailpiece 2-1/16" (Other Lengths Available)
18	#08038	H552	Locking Ring
19	#08037	H553	"O" Ring
20	#08033	H5/3/2D	3//" Control Ston Panair Vit
20	#08032	H541ASD	3/4" Control Stop Repair Kit Control Stop Repair Kit For 3/4" or 1"
	#08471	H790A	1" Screwdriver Stop
21	#08469	H790A	3/4" Screwdriver Stop
22	#80793	H1012A	C. P. Cover

SLOAN REGAL

TROUBLESHOOTING AND MAINTAINING THE REGAL FLUSH VALVE

1 PROBLEM: VALVE CLOSES OFF IMMEDIATELY

CAUSE: A) Ruptured or damaged diaphragm.

B) Enlarged by-pass orifice from corrosion or damage.

SOLUTION: A&B) Install new diaphragm or inside parts kit to correct above problems and update flushometer.

2 PROBLEM: LEAKING AT HANDLE ASSEMBLY

CAUSE: A) Handle seal may have deteriorated.

B) Handle gasket has been omitted.

C) Valve is old style and handle packing is worn.

SOLUTION: A) Install new seal or handle repair kit.

NOTE: The handle seal will easily slide right onto

the bushing if it is wet. **B)** Install handle gasket.

C) Install handle repair kit.

3 PROBLEM: LENGTH OF FLUSH TOO SHORT

CAUSE: A) Diaphragm assembly and guide assembly are

not hand tight.

B) Enlarged by-pass orifice from corrosion or damage.

or damage.

C) Black urinal relief valve in closet flushometer.

D) Low consumption kit installed in non-low consumption fixture.

E) Handle assembly is worn.

SOLUTION: A) Screw the two assemblies hand tight.

B) Install diaphragm or inside parts kit.

C) Install proper white closet relief valve.

D) Replace with proper inside parts kit .

E) Install handle repair kit.

4 PROBLEM: LENGTH OF FLUSH TOO LONG OR

FAILS TO CLOSE OFF

CAUSE: A) Relief valve is not seating properly or by-pass

orifice is clogged because of foreign material, or bypass orifice is closed by an invisible gelatinous film

from "overtreated" water.

B) Line pressure has dropped and is not sufficient

to force relief valve to seat.

C) White closet relief valve has been used in a

urinal valve.

D) Inside cover is cracked or damaged.

SOLUTION: A) Disassemble the working parts and wash

thoroughly.

NOTE: Size of the orifice in the by-pass is of utmost importance in the proper metering of water into the upper chamber of the valve. Do not enlarge or damage this orifice. Replace inside kit if cleans-

ing does not correct problem.

B) Shut off all control stops until pressure has been restored, then open them again.

C) Replace with black urinal relief valve.

D) Replace the inside cover.

CALL FOR TECHNICAL ASSISTANCE!

5 PROBLEM: INSUFFICIENT VOLUME OF WATER TO ADEQUATELY SIPHON FIXTURE

CAUSE: A) Control stop not open enough.

B) Urinal valve parts inside a closet valve.

C) Low consumption valve installed on a non-low consumption valve fixture.

 Water saver kit installed in old, non-water saver bowl.

saver bowl.

E) Inadequate volume or pressure at supply.

SOLUTION: A) Adjust control stop for desired delivery of water.

B) Replace inside urinal parts with proper closet valve parts from EQUIPARTS.

C) Replace with proper inside parts kit.

D) Position refill head on guide so that side 1

is in up position.

E) If no gauges are available to properly measure supply pressure or volume of water at the valve, then remove the relief valve from the inside parts kit, reassemble the valve, and open the control stop.

If the fixture siphons, more water volume is required. If a 3.5 GPF inside parts kit is installed in the valve, then first flip the refill head (under the diaphragm) to obtain a 4.5 GPF volume. If this volume is still inadequate, remove the flow ring from the guide to obtain a 6.5 GPF volume. If additional flow is still required, try a low pressure guide kit.

If fixture does not siphon or if a low consumption fixture is installed, or if the above steps do not prove satisfactory, steps must be taken to increase the

pressure and/or supply.

6 PROBLEM: LEAKING AT TOP OF VACUUM BREAKER

CAUSE: A) Rubber vacuum breaker boot or gasket has

, deteriorated.

SOLUTION: A) Install new vacuum breaker repair kit.

7 PROBLEM: LEAKING AT BOTTOM OF VACUUM BREAKER

TUBE OR AROUND COUPLING

CAUSE: A) Coupling gaskets have deteriorated.

B) Spud washer and/or spud have deteriorated.SOLUTION: A) Install proper new coupling gasket kit.

B) Install proper new spud washer and/or complete

new spud assembly.

8 PROBLEM: LEAKING BETWEEN VALVE AND CONTROL STOP

CAUSE: "O" ring and/or locking ring have deteriorated.

SOLUTION: Replace "O" ring and locking ring simultaneously.

9 PROBLEM: CHATTERING NOISE IN FLUSHOMETER

CAUSE: A) Diaphragm has been installed upside down.

B) Inside cover has become distorted from wear,

freezing or abuse.

SOLUTION: A) Replace the segment diaphragm to the proper

position as instructed by markings on the diaphragm.

B) Replace inside cover.